


DUSS

Bohrhammer P 26 SDS



	Teile-Nr.	Bestell-Nr.	Stück je Maschine		Teile-Nr.	Bestell-Nr.	Stück je Maschine
Schraubhandgriff	1	P26SDS/1	1	Rillenkugellager	62	P26SDS/62	1
Einlegemutter M10	2	P26SDS/2	1	Kurbelrad	63	P26SDS/63	1
Klemmring	3	P26SDS/3	1	Axialscheibe	64	P26SDS/64	1
Kreuzgriffschraube	4	P26SDS/4	1	Linsenkopfschraube 4x48	65	P26SDS/65	2
Sechskantmutter M5	5	P26SDS/5	1	Luftleitflansch	66	P26SDS/66	1
Anschlagstange	6	P26SDS/6	1	Feldpaket	67	P26SDS/67	1
Tülle	7	P26SDS/7	1	Linsenschraube 3,5x30	69	P26SDS/69	2
Zylinderschraube M5x20	15	P26SDS/15	4	Umschalthebel	70	P26SDS/70	1
Bohrkopfdichtung	17	P26SDS/17	1	Linsensenkschraube M4x10	71	P26SDS/71	1
Doppelabstreifer	18	P26SDS/18	1	Linsenkopfschraube 3x10	73	P26SDS/73	4
Nadellager	19	P26SDS/19	1	Kohlebürste	74	P26SDS/74	2
Ring	20	P26SDS/20	1	Kohlehalter	75	P26SDS/75	2
O-Ring 9x3	21	P26SDS/21	4	Motordeckel	76	P26SDS/76	1
O-Ring 24x4	23	P26SDS/23	1	Nadelhülse	78	P26SDS/78	1
Quadring	24	P26SDS/24	1	Senkschraube M5x8	79	P26SDS/79	1
Bohrspindel	25	P26SDS/25	1	Rastenfeder	80	P26SDS/80	1
Haltestift	26	P26SDS/26	1	Kugel Ø 4mm	81	P26SDS/81	1
Nadelrolle	27	P26SDS/27	4	Zylindergehäuse	82	P26SDS/82	1
Kupplungsfeder	28	P26SDS/28	1	Linsenkopfschraube 4x25	83	P26SDS/83	6
Anlaufscheibe	29	P26SDS/29	2	Schaltwelle	84	P26SDS/84	1
Sprengring	30	P26SDS/30	1	O-Ring 12x1,5	85	P26SDS/85	1
Sicherungsring	31	P26SDS/31	1	Zylindergehäusedichtung	86	P26SDS/86	1
Dämpfscheibe	32	P26SDS/32	3	Kondensator	87	P26SDS/87	1
O-Ring 35x5	33	P26SDS/33	1	Dämpfer-Zylindergehäuse	88	P26SDS/88	1
Dämpfring	34	P26SDS/34	1	Schalter	89	P26SDS/89	1
Sprengring	35	P26SDS/35	2	Schalterschutz	90	P26SDS/90	1
Runddrahtsprengring	36	P26SDS/36	1	Dämpfer-Motorgehäuse	91	P26SDS/91	1
Zylinder	37	P26SDS/37	1	Schalterhandgriff	92	P26SDS/92	1
Linsenschraube 3,5x20	39	P26SDS/39	4	Linsenschraube 5x30	93	P26SDS/93	4
Kegelritzelrad	40	P26SDS/40	1	Linsenkopfschraube 4x20	94	P26SDS/94	2
Rillenkugellager	41	P26SDS/41	1	Abstandsbuchse	95	P26SDS/95	4
Zylinderlager	42	P26SDS/42	2	Linsenkopfschraube 4x14	96	P26SDS/96	6
Getriebepatte	43	P26SDS/43	1	Kabelklemme	97	P26SDS/97	1
Kupferdichtring M5	44	P26SDS/44	6	Kabelschutzschlauch	98	P26SDS/98	1
Zylinderschraube M5x16	45	P26SDS/45	6	Kabel mit Stecker	99	P26SDS/99	1
V-Ring	46	P26SDS/46	1	Manschette	201	P26SDS/201	1
O-Ring 18x2	47	P26SDS/47	1	Futterhülse	202	P26SDS/202	1
V-Ringscheibe	48	P26SDS/48	1	Sicherungsring	203	P26SDS/203	2
Rillenkugellager	49	P26SDS/49	1	Haltering	204	P26SDS/204	1
Sicherungsring	50	P26SDS/50	1	Futtring	205	P26SDS/205	1
Anker	51	P26SDS/51	1	Anschlagring	206	P26SDS/206	1
Rillenkugellager	52	P26SDS/52	1	Feder	207	P26SDS/207	1
Lagergummi	53	P26SDS/53	1	Schaltfeder	208	P26SDS/208	1
O-Ring 16x5	54	P26SDS/54	1	Hülse	209	P26SDS/209	1
Schläger	55	P26SDS/55	1	Kugel Ø 7mm	210	P26SDS/210	2
Kolbenring	56	P26SDS/56	1	Futter	211	P26SDS/211	1
Kolbenring	56p	P26SDS/56p	1	Döpfer	212	P26SDS/212	1
Kolbenbolzen	57	P26SDS/57	1	Typenschild	213	P26SDS/213	1
Federring	58	P26SDS/58	2	DUSS-Aufkleber	214	P26SDS/214	2
Kolben	59	P26SDS/59	1	Bohrkopf	215	P26SDS/215	1
Pleuel	60	P26SDS/60	1	Oberschale	216	P26SDS/216	1
Kurbel	61	P26SDS/61	1	Motorgehäuse	217	P26SDS/217	1