



All visible surfaces have to be free of surface defects /  
Sämtliche Sichtflächen müssen frei von Oberflächeneffekten sein

Missing dimensions please check 3D-data, 3D-data are generally binding /  
Fehlende Maße bitte den 3D-Daten entnehmen, 3D-Daten generell bindend

				general tolerance ISO 2768-mK	edge ISO 13715	Scale: 1:1	Weight: -
				toleration acc. to ISO 8015		Material: -	
Revision				Date	Name	Part name: <b>Dekorelement FS IN RFID</b>	
				Drawn	hosm		
				Check	hosm		
Rev. Description Date Author				Rel.	hosm	Drawing No.: -	
				Project No.: -	Article No.: -		
						Sheet: 1	of: 1
						Size: A3	